


Tungsten Carbide Rotary Burrs




➤ Cross / Diamond Cut

Cylindrical




STANDARD CUT	CROSS/DIA-MOND CUT	HEAD DIA	EDGE LENGTH	SHANK DIA
C-1	C-1 D	4	14	6
C-2	C-2 D	6	15	6
C-3	C-3 D	8	19	6
C-4	C-4 D	10	20	6
C-5	C-5 D	12	20	6
C-6	C-6 D	16	25	6
MC-1		3	15	3

Tree Radius




STANDARD CUT	CROSS/DIA-MOND CUT	HEAD DIA	EDGE LENGTH	SHANK DIA
TB-1	TB-1 D	6	15	6
TB-2	TB-2 D	10	20	6
TB-3	TB-3 D	12	25	6

Cylindrical End Cut



STANDARD CUT	CROSS/DIA-MOND CUT	HEAD DIA	EDGE LENGTH	SHANK DIA
CE-3	CE-3 D	8	19	6
CE-4	CE-4 D	10	20	6
CE-5	CE-5D	12	20	6

Conical



STANDARD CUT	CROSS/DIA-MOND CUT	HEAD DIA	EDGE LENGTH	SHANK DIA
A-1	A-1 D	6	20	6
A-2	A-2 D	10	20	6
A-3	A-3 D	12	25	6
MA-1		3	10	3

Cylindrical Ball



STANDARD CUT	CROSS/DIA-MOND CUT	HEAD DIA	EDGE LENGTH	SHANK DIA
B-1	B-1 D	6	15	6
B-2	B-2 D	8	20	6
B-3	B-3 D	10	20	6
B-4	B-4 D	12	20	6
B-5	B-5 D	16	25	6
MB-1		3	15	3

Cone Shape Radius




STANDARD CUT	CROSS/DIA-MOND CUT	HEAD DIA	EDGE LENGTH	SHANK DIA
K-1	K-1 D	10	20	6
K-2	K-2 D	12	20	6
MK-1		3	10	3

Tree Pointed




STANDARD CUT	CROSS/DIA-MOND CUT	HEAD DIA	EDGE LENGTH	SHANK DIA
T-1	T-1 D	6	20	6
T-2	T-2 D	10	20	6
T-3	T-3 D	12	25	6
T-4	T-4 D	16	30	6
MT-1		3	15	3

Ball



STANDARD CUT	CROSS/DIA-MOND CUT	HEAD DIA	SHANK DIA
S-1	S-1 D	6	6
S-2	S-2 D	8	6
S-3	S-3 D	10	6
S-4	S-4 D	12	6

Flame



STANDARD CUT	CROSS/DIA-MOND CUT	HEAD DIA	EDGE LENGTH	SHANK DIA
F-4	F-4D	12	24	6